

HAMPSHIRE

MAR 27 2006

Health

ES-76
Rev 11/04

STATE OF WEST VIRGINIA
SUBDIVISION APPROVAL APPLICATION FORM
HAMPSHIRE COUNTY HEALTH DEPARTMENT

I. General Information

Name of Applicant: North American Land Phone: 304-582-0935
Mailing Address: P.O. Box 190 Petersburg WV 26847
Property Owner (Name & Address): _____

Deed Recorded in Book: 439 Page: 255 County of: Hampshire
Tax District: Mill Creek Map: 28 Parcel: 17
Location of Property (be specific - map may be attached): 3 mi up Fox Hollow Rd
from Rt. 50

Total Acreage of Tract _____ Total Acreage to be Developed 448.784
Number of Lots to be Developed 48 Drinking Water Source _____

Type of Structure(s) to be Constructed: _____
Have any previous subdivision approvals or declaratory rulings been issued on this tract or adjacent tracts?
Yes No
If yes, give details _____

Signature of Applicant Stephen A. Little Date 3/24/06

II. Check List

- Three (3) copies of plat plan of property (show lot layout, lot dimensions, lot numbers, streets, location of percolation test holes and six foot test holes, location of wells and public water lines, location of 10,000 square foot reserve area) must accompany this application.
- * In addition, a site visit of the proposed subdivision must be made by the appropriate Health Department representative prior to permit issuance.
- * A \$100 per lot permit of approval fee must accompany any application.

III. For Health Department Use Only

Approval Issued Yes No Date: _____

By: _____ Date Received: 3-29-06 Receipt Number: 2934

**REPORT SHEET
FOR
PERCOLATION AND SIX FOOT HOLE TESTING**

Subdivision Name Hamilton Estates County Hamp.
 Total Number of Lots 49 Name of Applicant North American Land
 Name of Certified Installer Responsible for Testing Meade's Special Services
 Installer Certification No. 54-94-0222 Installer Signature Wendell Meade
 Address P.O. Box 188 Capon Bridge

Type System	Lot Number	Percolation Test Results (Minutes per Inch of Fall)				Average Results	Six Foot Hole Results		Date Conducted
							Depth to Water	Depth to Rock	
II	1	240	60	90	144	22	6'		2/20/06
II	2	60	60	60	60	10			
I	3	144	180	120	180	26			
I	4	72	65	60	60	11			
I	5	360	360	360	360	60 ⁴⁵			
II	6	120	180	240	180	30			
I	7	180	180	144	180	29			
II	8	360	240	360	240	50			
II	9	180	180	240	180	33			
I	10	360	360	360	240	55			
I	11	180	144	240	240	34			
I	12	360	180	240	480	53			
II	13	360	480	480	360	90 ⁶⁰			
I	14	180	205	144	144	28			
I	15	180	240	180	180	33			
I	16	360	180	240	360	48			
I	17	240	180	240	180	35	6'		
II	18								
I	19	360	360	360	360	60	5'		
II	20								3/22/06

(Attach additional pages if needed)

April 4

REPORT SHEET
 FOR
 PERCOLATION AND SIX FOOT HOLE TESTING

Subdivision Name Hampton Estates County Hamp.
 Total Number of Lots 49 Name of Applicant North American Land
 Name of Certified Installer Responsible for Testing Meade's Special Services
 Installer Certification No. 54-94-0222 Installer Signature Wendell Meade
 Address P.O. Box 188 Capon Bridge

Type System	Lot Number	Percolation Test Results (Minutes per Inch of Fall)					Average Results	Six Foot Hole Results		Date Constructed
								Depth to Water	Depth to Rock	
II	21	60	60	103	60	12	6'		2/20/06	
II	22	120	120	144	360	31				
I	23	120	180	144	240	29				
I	24	240	180	180	180	33				
I	25	60	60	60	60	10				
II	26	120	144	120	120	21				
II	27	60	60	103	120	14				
II	28	180	180	180	180	30				
I	29	103	144	240	240	30				
I	30	120	180	144	120	24				
II	31	240	120	240	180	33				
I	32	180	360	240	120	38				
I	33	180	144	206	180	30				
II	34	103	90	90	90	16				
II	35	60	90	90	60	13				
II	36	240	180	144	360	39				
I	37	180	240	144	120	29				
II	38	180	144	120	144	25				
II	39	240	144	360	240	41				
II	40	120	180	144	120	24	6'		3/22/06	

on site

(Attach additional pages if needed)

**REPORT SHEET
FOR
PERCOLATION AND SIX FOOT HOLE TESTING**

Subdivision Name Hamilton Estates County Hamp.

Total Number of Lots 49 Name of Applicant North American Land

Name of Certified Installer Responsible for Testing Meade's Special Services

Installer Certification No. 54-94-0232 Installer Signature Wendell Meade

Address P.O. Box 188 Capon Bridge

Type System	Lot Number	Percolation Test Results (Minutes per Inch of Fall)					Average Results	Six Foot Hole Results		Date Conducted
								Depth to Water	Depth to Rock	
II	41	360	180	240	180	40	6'		2/20/06	
II	42	120	180	144	180	26				
I	43	360	180	144	206	32				
II	44	188	180	144	180	29				
II	45	144	180	180	206	30				
II	46	120	144	120	180	24				
II	47	180	240	240	144	34				
II	48	120	206	180	240	31				
II	49	180	180	240	180	33			3/22/06	
I	5	240	360	180	240	43			3/24/06	
II	13	120	240	360	240	40	6'		3/24/06	
II	18	360	180	240	240	43	5'		3/24/06	
I	19	240	120	360	240	40	6'		3/24/06	
II	20	144	240	360	360	46	5'		3/24/06	

*2-
done*

(Attach additional pages if needed)