

Hampshire County Health Department

HC 71, Box 9 Augusta, WV 26704

Nursing: (304) 496-9640 Environmental: (304) 496-9641 Fax: (304) 496-9650

December 22, 2006

Hampshire County Planning Commission PO Box 883 Romney, WV 26757

Dear Sirs:

This office has reviewed a plat of survey for WV Hunter, LLC to approve a subdivision called Bluffs on the Potomac Section 7 located on Graces Cabin Road, and further referenced as Tax District Romney, Tax Map 33, Parcel 3, Deed book 436, Page 638. This subdivision section consists of 10 lots containing 205.01 acres. All lots contain a sewage disposal area of 10,000 square feet where no development or structures other than the septic system shall be permitted. These lots are to be developed with individual wells and septic systems to serve single family dwellings.

Percolation test results are within limits as set forth by West Virginia CRS 16-1. Six foot soil observation holes indicate no restrictions due to water table or shallow bedrock within the designated sewage disposal area except as noted on the Health Department subdivision application.

The plat of survey dated 10/16/06, is hereby approved by the Hampshire County Health Department. Any changes or revisions to the Health Department stamped and signed plat, or subsequent final plats approved based upon the approved plat, will make this approval null and void.

This approval is not permit for individual water systems or individual sewer systems. Applications for permits must be made separately to the Hampshire County Health Department.

Sincerely,

Terry Mayhew, RS

CC: WV Hunter, LLC

Sung Maule

REPORT SHEET FOR PERCOLATION AND SIX FOOT HOLE TESTING

Subdiv	ision Nan	ne <u>Blu</u>	iffs or	y The	Potor	iac_c	ounty	Han	nps	hir-	<u>e</u>	
			Sect 7) N									
Name (of Certific	ed Installe 5° cation No.	r Responsil	ble for Test Installe	ing <u>Ju</u> er Signatu ss <u>HC G</u>	re <u>N</u>	ery « 16.	4nu	Kom	ney,	P.T.E.	7. 2675
Туре	Tyme Let					Average	Six Foot Hole Results				Date	
System	Number		on Test Results (Minutes per Inch of Fall)		Results	Depth to Water		N/A		5-5-06	1	
エ	184	105	95	100		28.1	-	(1	Í .	5504	
#1111	185	150	90	165	190	15.6		f				
<u>+</u> _	186	110		90	100	14.5	Ÿ	<u> </u>				2
<u>+</u> _	186	95	80	75					·		-	,
1_	188	108	105	75	90	15.7						1
	189	176	175	150	178	28				-		
II_	190	175	150	130	180	26.4			-		-	1
II	191	205	100	190	198	28.8						1
IF	192	165	190	155	140	27		(A)				1
I	193	95	105	150	180	22	<u>.</u>					$\left\{ \right.$
						1						
*//						ļ						
			(d.)					N.				
) 								×				
											ļ	4
			*	C.+ 10	6 Has	2 00	Paid	cd 5-1	4			4
	1			L.+ 18	8 peac	de Las	15	7	-		-	4
/ <u></u>				See At	Fached	heat	Pse	lit	180		-	-

(Attach additional pages if needed)

- Section 7

REPORT SHEET PERCOLATION AND SIX FOOT HOLE TESTING

(Section 7) - Re-Perk

me of	Certifie	d Installer	Responsib	ole for Tes	ting	re Ju	W Can	pentel Bridge w	N 26711
ype	Lot	Address HC 61 Percolation Test Results (Minutes per Inch of Fall)				Average Results	Six Foot He Depth to Water	Depth to Rock	Date Conducted
stem	Number	Percolation	170	+600	770	287	3	0-	12-6-06
	188	108	194	180	120	23,0			12.500
<u> </u>	100	100				-			
-	,								
						-			
	-	-				_			
		-							
	-	-							
	-	1				1			
	-						-	_	18
		-							
		+	-						
	-	-			K				_
									-
					3	(*)			
			_	_		ellisie ou			_
					-				
							L		
					1	1 .	2.4 H		1

(Attach additional pages if needed)