

PERMEATION AND SOX FOOT HOLE TESTING

Substation Name: Ranch View Estates County: Hammshire
 Total Number of Lots: 24 Name of Applicant: M. Puno
 Name of Certified Installer Responsible for Testing: Bob Williams
 Installer Certification No.: _____ Installer Signature: [Signature]

Lot No.	Permeation Test Results (Minutes Per Inch of Fall)				Average Result	Sox Test Results		Date Conducted	
	Depth to Rock	Depth to Rock	Depth to Rock	Depth to Rock		Depth to Rock	Depth to Rock		
110	1	80	45	59	30	53.5	Get	Get	10/25/04
18"	2	55	70	73	68	54			
18"	3	81	46	60	61	62			
18"	4	23	30	27	33	28.5			
18"	5	50	55	50	60	54			
18"	6	40	35	57	43	42			
18"	7	57	52	58	40	52			
24"	8	31	37	39	28	31			
24"	9	41	40	32	51	41			
24"	10	23	37	30	33	31			
24"	11	18	16	21	27	19			
24"	12	39	41	48	35	41			
24"	13	48	36	47	38	42			
24"	14	22	28	27	31	27			
18"	15	70	82	81	55	72			
18"	16	62	72	46	44	57			
C.O. 10"	17	40	32	27	30	32			
C.O. 10"	18	33	27	31	40	32			
C.O. 10"	19	17	21	21	25	21			
C.O. 18"	20	20	21	30	17	22			
24"	21	41	38	31	25	36			
24"	22	31	37	38	42	35			
24"	23	25	31	20	18	24			
24"	24	19	23	18	26	21			

(Attach additional pages if needed)

C.O. = Customer Data in CLASS II box